

Info Sheet for...

Easy-Glide & Easy Go



Fast wax for glide. 60ml.
Universal -10..+10C / +14..+50F

1. Spread a thin layer over the glide zone.
 2. Let dry for 3 minutes.
 3. Brush with a nylon brush.
- Good to go.

No scraping needed!

Easy-Glide protects your skis.
Unlike similar products on the market, Easy-Glide contains no solvents that make your ski base hard and dry.
Protect the bottle from freezing.

Modern fast waxes make it easy to wax.
Apply and ski -- Can it be easier?

Fast wax for kick. Two Choices.
Easy-Go Minus -1..-15C / 30..5F
Easy-Go Plus +1..+10C / 34..50F

1. Apply
2. Let Dry.
3. Ski



No corking needed!



Official Supplier to numerous National Teams in Sweden, Norway, Finland, Russia and Canada.



For more information contact Skigo or visit your local retailer.